



## Tensil Strength

Applicant: POLYROOF SAC  
Address: Calle Eucaliptos del Sector Santa Genoveva, Lote 1 -C2  
Tax Id: 20553429201  
Sample: TK6 2.00 mm white, also applies for TK9  
Test: Tensil Strength  
Test Conditions: Ambient temperature, relative humidity 58%, and 74° Farenheit

### Results

Test Method	Unit of measurement	Description	Values
ASTM D5628 - 18	Stress (Mpa)	Strain	32.53
		Fracture	27.56
	Stress (Psi)	Strain	4,729
		Fracture	4,007
	Elongation (%)	Strain	4%
		Fracture	56%



**Patricio Rubio**  
GERENTE DE PROYECTOS

Celular: (+51) 922 242 447

Fijo: (511) 713-4713

Dirección: Calle Eucaliptos del Sector Santa Genoveva,  
Lote 1 - C2 - Sub lote B-1, Nave 6. LURIN. LIMA - PERÚ

Website: [www.klar.com.pe](http://www.klar.com.pe)

[www.klar.com.pe](http://www.klar.com.pe)